

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




FIG. 1A




FIG. 1B




FIG. 2A




FIG. 2B




FIG. 3

Repair information	
Product name	<input type="text"/>
Manufacturer name	<input type="text"/>
Type number	<input type="text"/>
Warranty period	<input type="text"/>
State of failure:	<div></div>

FIG. 4

64

Component information database

Component name	Type number of component	Product name	Type number of prduct	Provider of product	Others
Memory	O011-64	Personal computer	1987-115	P	64MB, No parity
Disk	Y015-1G	Personal computer	432-5G	Q	1GB, Built-in, IDE
.
.
.

FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13